

S74 Rev 168 Rings Occ
2012 / 180

Rev 168 ①

June 27-28, 2012

ACE Herter Reed

NOPC: Lu

Ops Room: Aseel, Elias, Danny, Don ~~over~~,
Gssam. Summer students, Sami

David R will be
supporting from
Innovec

C610 RS Pass. 2-way Ring Occ DSS-43 Briefings

No TLM

D/L only X&S S 085004

X available @ BOT

Uplink time 080000 18 kW X LCP

EOT 180/143500

Weather overcast. Ø wind

Equipment green

0625 Lu called. Scheduled WVS2 playbacks for 8 hrs after EOT

RSRs subchannels: 1, 16, 50, 100 kHz

WVS2 Ka : 1, 2, 16, 50 kHz
1-way

Fgain	43 X	60	34 X	55
	43 S	50	34 Ka	55

no TOS Weak S-band signal from ground.

Check into that

~18 dB

C726 Station asking if signal is intermittent & S-band
→ yes intermittent. Seems ground
1-way

Say freq. flat, so it's ground.

→ not much they can do. They are in C:

0730 NORC telling station that they too see a spike. Is it possible that they have S-band transponder on.

→ Not according to their displays.. & if transponder, it

0734 Told 43 ^{spur} signal is getting stronger & it will be a problem when we start recording data. Is engineering staff available to investigate?

→ Engineering staff left about an hour ago.
Will check. Manager is still on-site

0739 Station asked if we're seeing on both LVAAs
→ not sure what you mean. We have RSR & WVSR looking @ it.

→ They have Maser & Heupt.. not sure how we are configured. Can we look @ Heupt
→ sure we can do that. Standby

0740 Danny switched to ECP. No signal

0743 Told station don't see it in LCP. Just RCP.

0744 NORC asking if switch from Maser to Heupt. Discuss over black phone.. Maser is better.
What's difference?

→ 8 K difference between the two, which translates to 1.8 dB off. (difference between two)

0752 Told NORC that if it doesn't take too long, we'll switch after the start of the 2-way baseline to see if 43 ^{spur} is gone. Can you check w/ station how long? LU → Switch 2 & switch 1?
We'll want:

RCP low noise going to OI output

Rev 168 (2)
6/27-28

0755 15 days ago the S-Maser was red @ 43 &
they fixed it but maybe problem

0800 Xmtr on 16.8 kW

0804 Lu said that Mitch said there ^{are} 4 switches
from LNA1 to IF output. 10, 11, 12, 13. Toggle & see
if it goes away.

- No impact to U/L
- No. S-band only)

0805 Nope asking station to toggle switches. OE
suggested. Tried dummy test & it worked

0807 Station toggled switches & still see signal

0808 43. Another suggestion:
more polarizers to see if signal follows
polarization

0809 Told NOPE we now see spur in both RCP &
LCP.

0809.50 Nope told station to put back in original
configuration

0812 Told NOPE spur is back to RCP only

0815 Lu on blk phone: suggest we switch now & not
mess up during expt.
→ we'll try & switch back if

0815 NOPE told to switch SRCP:
RCP low noise to LNAs to OI output

0816 NOPE said station completed switch
→ we'll monitor for a couple of minutes & let him know

- 0818 Told NOPG we still see it.
- 081840 Switched back to Maser
- 0820 Lu said station back in Maser config.
- 0827 Station said they want to switch RCP to LCP
 → signal switched from RCP to LCP
↓
During WCSR
- 0832 Station said one more thing
 they want to try .. switch LNFT
 → No spur in RCP.
 LCP freq not seeing anything
 → correct. They had to disconnect LCP.
- 0836 Told station don't see spur in RCP
 → Yes, won't see if it's in the load. Is SLC out of equation?
~~me~~ Yes. Not earth pointed & S-band not on.
~~as~~ makes sense
- 0837 will take it out of the load
 → signal back
- 083755 43: Signal path back to normal @ this time.
- 08381 Told 43 spur is in both RCP & LCP ($\approx 18-20 \text{ dB-Hz}$)

0855 34 Briefing

RS support. ZWUW nbg acc.
 tracking X & Ka
 No signal
 SLC Earth pointed 100923
 BOT 09500. EOT 141500
 NO TIN

Equipment: Green
 Weather: Overcast

Rev 168 (3)
6/27-28

0858 Ace making sure that 34 support is DL only (after I asked him if they are aware of that & that we have shorter pre-cal than usual).

0901 NOPG asking what team
→ Team △

Previous team is BRAVO

~ 0912 Spur switching between RCP & LCP

0907 Told 43 we are seeing spur switch between RCP & LCP
so assume they are ~~doing something~~ changing configuration?
43 → that's a negative! Not changing anything

0935 Att auto

0938 Start movie

0940 Start rec

DR # 108835
for S-band spur

0940 Spur is @ -3662

0955 Asked Cesarbera ^{43 & 31} to enable SNT on all DL channels

43 X 22.242

43 S 19.5560

34 X 21.9

34 Ka 42.5

0957 Told 43 & 31 to disable all except X @ 34

1000 Asked 34 for weather update

Overcast & Ø wind

1003 Lu asking 34 to change Rx to -135 @ DCOLE
& Ka-band RCP put switch 43 in Alpha position for monopulse operations

1006 Started seeing X-band
100630 Ka-band signal

100940 S-band

A3 1/L

1011 34 1/L Ka

101140 34 1/L X

101530 Asked 34 to enable monopulse
Signal dropped! Got to S & asked station to
enable monopulse
Asked 34 to disable mono ~~& clear~~ hear
& clear offsets

Signal went back.

1019 Station asking if can do on-point phase cal
→ Do they need cal in 1-way & 3-way or 1-way sufficient?
→ Just 1-way. How long? → 5-7 mins

Gave station ok to do on-point phase cal.

102050 Station ok to do on-point phase cal.

1021 Lu thinks they had wrong switch config.
A3 in B position when they did cal
→ told Lu can they use offsets from 1019
last ORT

102740 Station said expect to finish cal @
1031. Enable mon. @ that time
→ give me new tan value & then
decide on mono

1031 Lu said they were in A3 in B position when
they did cal.

Tan value from 1019 ORT was 140.
Average between 1-way & 2-way

(4)
Rev 168
6/27-28

1034 Told station 2 mins from switching

↳ 2-way Cal not completed?

→ Completed. Looking for Tau value

34 Found it: 140 . stand by on mono enable

NOPE said they have gain & phase in system
from switch A3 in B position. Tau is correct but
phase & gain not.

103735 Switch to coherent mode
34-Spur

1039 SS Lu found phase & gain value from
ORTC on 1609

104130 Lu giving station new phase & gain from
log: told them problem was that cal was w/
switch A3 in B position
Phase 44.912
Gain 0.335
Enter

104245 34 enabled mono w/ ~~same~~ phase &
no improvement. & more stable
(from u49.6 to u50.1)

34 said error in BM

6.3.1 section 5.

caused this problem

→ Lu: said this directive has been there for
year not only Camberra but also Goldstone
& Madrid

Discussion bet. 34 & Lu .. 34 thinks that
section needs classification & it was
direct cause of problem for driving
monopulse off

1050 P/N

43 X	55.53
43S	44.22
34 X	49.5
34Ka	50.0

1055 Lu said will put a comment to make item #5 clearer. Add more comments.

34 → It's very prudent that they do open a DR?

Lu → pushed me. Thought

me → Thought DSN wants to document (new) problem

Lu → Yes, I'll take this one.

Even though they've been using some for years, prob. shift change @ pre-cal & didn't handover. & NOPEs were busy w/ 43 spur problem.

DR# C108836

1005 Asked ACE if he heard 43 say xmtr off.

→ Pretty sure he did

Then ACE said his displays show xmtr is still on
he thinks xmtr off is 113800

→ Told him it's 1050 per timeline
but no harm in keeping it on

During this Lu asked if 43 xmtr should be off
→ Haven't seen at ACE 1138.

Talk more w/ Herken. He asked how we determine uplink time.
Explained it to him. He realized he only has 1 pause of timeline!!

(5)

- 113745 43 reports Xntr off Rev 168
1143 Told 43 & 34 we started going through 6/27-28
- 1145 Told 34 if monopulse gets disabled
anytime during the expt bcc. signal gets
weakened, pls let us know & we'll decide
whether we want to re-enable or keep
disabled
- 1146 34 reported they had momentary LOS
rings. There maybe some intermittent drops,
but once we get to ring B in 120439, they
likely lose the signal until we exit ring B.
- 120141 Told 34 we believe mono was disabled
so can they re-enable
Corrections very small: u1! for both. EL
a little higher. m.s (n average)
- 120630 Mono disabled
Told station will keep mono disabled & let
them know when to reenable
- 1208 Lu asked 34:
On DCOS, configure to open-loop mode
- 123125 34 reporting 1/L
1232 34 ka O/L
1234 Told 34 signals are back to full strength.. (enable mono
noticed rev was O/L). when you lockup on signal
123425 Mono enabled

W1302 X O/L

131050 43 S-band O/L

1315 Told 43 & 34 that we'll record n20
mins of noise baseline & then do quick
SNT & then be done. So it should be
done in n25 min

43 asking if they should configure
open-100P

→ not needed. Only 34 & I will
check w/ NOPE if they already did
that

→ yes they did

1334 SNT measurement

43 X 21.616

43 S 24.946

34 X 26.8

34 Kz 61.9

Playback

180/0940 - 1335

1336

Stopped recording & we are
done w/ experiment. Overall, things went v. well
see the DSS-43 S-band spur
& data looked good. The DSS-43 S-band spur
continued to appear in 1-way recordings, but since
coherent data are prime, that should hopefully be
of no impact to data. Also, the initial mono
problem was resolved quickly & before the official
start of the baseline, so that was of no impact.

The experiment was a success. Thank you for a great support! Plz wait for ACE to
release you. 133745 stations released