SPAM					
ERROR NUMBER SPLAT	RESPONSIBLE TEAM	TIME	REQUEST	PROBLEM	PROPOSED SOLUTION
S97000269	ENGR RSS SP	2016-340T01:20:00			Monitor during OTM466 and 467 development, prepare realtime commands if OTB windows not used