

Input Files
z0680b_for_S69.cf SCLKSCET.00147 091005AP_LT_09248_17265.TXT CAS_10001_17182.VP 091005AP_OP_09248_17265.TXT S69_SIP_PORT1_GEOEPOCHS_110121.sasf S69_SIP_PORT1_RIDEREPOCHS_110307.sasf SP_S69_SIP_PORT2_DATAPOL_110310.sasf SP_S69_SIP_PORT2_PDT_110310.sasf ULO_S69_SIP_PORT2_ATT_110309.sasf ULO_S69_SIP_PORT2_SFOS_110309.sasf CAPS_S69_SIP_PORT1_110228.sasf CDA_S69_SIP_PORT1_110228.sasf CIRS_S69_SIP_PORT2_110311.sasf INMS_S69_SIP_PORT2_110314.sasf ISS_S69_SIP_PORT2_110314.sasf MAG_S69_sip_port2_110314.sasf MIMI_S69_SIP_PORT1_110223.sasf NAV_S69_SIP_PORT1_110228.sasf RADAR_S69_SIP_PORT2_110314.sasf RPWS_S69_SIP_PORT2_110311.sasf RSS_S69_SIP_PORT2_110314.sasf UVIS_S69_SIP_PORT1_110228.sasf VIMS_S69_SIP_PORT2_110314.sasf SI_S69_SIP_PORT2_110310.sasf VIMSIOPS_S69_SIP_PORT1_110228.sasf AACS_S69_SIP_PORT1_110218.sasf CDS_S69_SIP_PORT2_110311.sasf OPMODE_S69_SIP_PORT2_110314.sasf
This Merge Has No Files From
ISSIOPS
IVD Files
RSS_S69_SIP_151_110107_V2.ivd

SPAM						
ERROR NUMBER	RESPONSIBLE TEAM	TIME	REQUEST	PROBLEM	PROPOSED SOLUTION	
TIMING ERRORS						
(all dispositioned)						
EARTH POINT ERRORS						
(none)						
VELOCITY AND ACCELERATION ERRORS						
(none)						
COMMANDS EXPANDED OUTSIDE OF SEQUENCE						
(none)						
TARGET OPTION LABEL ERRORS						
(none)						
PRECISION ERRORS						
(none)						
Duplicate Epochs						
(none)						
LMB Warnings						
(none)						
SEQEN Violations Summary						
sameSecondCommandConflict-0	SCO	2011-184T11:11:10	SP-SMT_150NA_OBSERV184_NA_SPSPR, SP-SMT_LOAD_TAB_01	6CHG_CRC_NP, 6MOD_POL_TBL	Both Commands from SMT request.	
sameSecondCommandConflict-1	SCO	2011-184T11:11:13	SP-SMT_LOAD_TAB_01, SP-SMT_150NA_OBSERV184_NA_SPSPR	6MOD_POL_TBL, 6SSR_CONFIG	Both Commands from SMT request.	
sameSecondCommandConflict-2	SCO	2011-184T11:11:14	SP-SMT_LOAD_TAB_01, SP-SMT_150NA_OBSERV184_NA_SPSPR	6MOD_POL_TBL, 6SSR_CONFIG	Both Commands from SMT request.	
sameSecondCommandConflict-3	SCO	2011-184T11:11:15	SP-SMT_150NA_OBSERV184_NA_SPSPR, SP-SMT_LOAD_TAB_01	6CHG_CRC_NP, 6MOD_POL_TBL	Both Commands from SMT request.	

SP Merge Error Report (SPAM)

sameSecondCommandConflict-4	SCO	2011-184T11:11:18	SP-SMT_LOAD_TAB_01, SP-SMT_150NA_OBSERV184_NA_SPSPR	6MOD_POL_TBL, 6SSR_CONFIG	Both Commands from SMT request.
SEQGEN_log1	NAV/ISS_SI		NAV_151SK_KODAKMO001_PRIME	ERROR Duplicate request id: NAV_151SK_KODAKMO001_PRIME in FOREGROUND. request removed from input.	
SMT ERRORS					
(all dispositioned)					
AP DOWNLINK CHECKS					
ap_downlink_1			Warning: 70m usage for sequence exceeds project commitment of <= 35%; is at 47%		To be resolved pending DSN allocation negotiations. S. Brooks
SPASS//SASF COMPARE					
CIMS_SPASS_SASF_0140	SP	2011-188T01:55:00	SP_150EA_C34BWGNON188_PRIME	This rolling downlink contained 0 7DELTA_BASE BODY_LONG command(s) in the SASF. There should be multiple.	SP to update CIMS.
CIMS_SPASS_SASF_0145	SP	2011-192T01:39:00	SP_150EA_C70METNON192_PRIME	This rolling downlink contained 0 7DELTA_BASE_LONG command(s) in the SASF. There should be one.	SP to update CIMS.
CIMS_SPASS_SASF_0148	SP	2011-206T18:22:00	SP_151EA_G34HEFNON206_PRIME	This rolling downlink contained 0 7DELTA_BASE BODY_LONG command(s) in the SASF. There should be multiple.	SP to update CIMS.
CIMS_SPASS_SASF_0150	SP	2011-212T18:06:00	SP_151EA_G70METNON212_PRIME	This rolling downlink contained 0 7DELTA_BASE_LONG command(s) in the SASF. There should be one.	SP to update CIMS.
RESOURCE CHECKER					
(all dispositioned)					